



6 oz Machine



12 oz Machine

Popping Instructions

1. Turn on all switches (light, kettle warmer, kettle motor)
2. Allow kettle to heat about 3-4 minutes (when starting a cold machine)
3. Pour kernels and oil mixture into kettle.
4. When kernel's are almost done popping turn off kettle motor
5. Empty kettle immediately after popping stops
6. If making more popcorn repeat steps 3-5
7. After the final batch, turn the kettle heat and kettle motor switch off, but remember to leave the light on.
8. **CAUTION** MACHINE PARTS GET HOT. HANDLE WITH CARE.**

Cleaning of machine

1. Turn off all switches
2. Empty all unused popcorn from the kettle and inside the machine.
3. Empty the kernel pan

Crown Rental is responsible for the main washing of the machines. You are not required to do any washing.